



YORKSHIRE OF EDINA SENIOR LIVING
Edina, MN

Photo of fourth floor common spa room showing ceramic tile detail.

YORKSHIRE OF EDINA SENIOR LIVING

Edina, MN

Photo of typical corridor showing final finishes and furnishings.





YORKSHIRE OF EDINA SENIOR LIVING

Edina, MN

Photo of typical unit kitchen showing final finishes and appliances installed.



YORKSHIRE OF EDINA SENIOR LIVING

Edina, MN

Photo of typical bathroom showing final finishes complete.



YORKSHIRE OF EDINA SENIOR LIVING
Edina, MN
Photo of fourth floor lounge space showing final finishes and furnishings.



YORKSHIRE OF EDINA SENIOR LIVING

Edina, MN

Photo of typical first floor corridor showing final finishes complete.

YORKSHIRE OF EDINA SENIOR LIVING

Edina, MN

Photo of first floor pub area showing final finishes and furnishings.



YORKSHIRE OF EDINA SENIOR LIVING

Edina, MN

Photo of main dining room showing furniture installed.





YORKSHIRE OF EDINA SENIOR LIVING
Edina, MN
Photo of fireplace seating area at main entry lobby.



YORKSHIRE OF EDINA SENIOR LIVING

Edina, MN

Photo of beauty salon showing final finishes and furniture installed.



YORKSHIRE OF EDINA SENIOR LIVING

Edina, MN

Photo of connection link between neighboring building showing progress of glass and exterior finishes.



YORKSHIRE OF EDINA SENIOR LIVING
Edina, MN

Photo of center courtyard area showing
landscaping and lighting installed.

YORKSHIRE OF EDINA SENIOR LIVING

Edina, MN

Photo of first floor bistro and pub area showing final finishes and furniture installed.

